

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

Date of Maintenance: _ Property Address:	ming maintenance activity 4-14-22 Reason 688 30 Th St value ZIP: 550	for Maintenance: P	Rowline roperty Owner's Na	ime: <u>Jason Se</u>		
, 51	:W7978K25992				er Service/ L167	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
 Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements) 		Sludge Level in Sludge + Scum	Liquid Level of Tank — in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
	curely replaced? Yes	□No	enter authorization co		ting depth or	
3. Is there evidence of		□ No ptic, holding, pretr	eatment or pump 1	tank below the opera	ting depth or	
3. Is there evidence of	curely replaced? Yes of tank leakage from a se ged, cracked, or structur Tank	□ No ptic, holding, pretr rally unsound main Leaking Out	eatment or pump tenance hole cover	tank below the operars? Yes No Cover Damage	ting depth or	
3. Is there evidence of	curely replaced? Yes of tank leakage from a se ged, cracked, or structur	□ No ptic, holding, pretr rally unsound main	eatment or pump t	tank below the opera	ting depth or	
3. Is there evidence of	curely replaced? Yes of tank leakage from a se ged, cracked, or structur Tank Septic/Holding Tank #1	No ptic, holding, pretrally unsound main Leaking Out Yes LNO	eatment or pump to tenance hole cover Leaking In	tank below the operators? Yes No	ting depth or	
3. Is there evidence of evidence of dama	curely replaced? Yes of tank leakage from a se ged, cracked, or structure Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	No ptic, holding, pretrally unsound main Leaking Out Yes No Yes No Yes No	eatment or pump to tenance hole cover Leaking In Yes No	tank below the operators?	ting depth or	
4. How many gallons Tank #1 / 2.00	curely replaced? Yes of tank leakage from a se ged, cracked, or structur Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	No ptic, holding, pretrally unsound main Leaking Out Yes No Yes No Yes No Yes No Yes No Read	eatment or pump to tenance hole cover Leaking In Yes No Yes No Yes No Yes No	tank below the operators?	gal	

Afton MN 55001 P: 651-439-4847 License Number: L1673