## GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## SSTS MAINTENANCE REPORT H3762B31289

Date of Maintenance 6/30/23	Reason for Maintenance			6
Property Address: 20665 Harr	OW ALE	Property Owner's Nan	ne: Matthew + Katherine	-
Municipality: Forest Lake	State WW Zi	p Code 55025	GEO Code/Property I.D. #:	SMin
A. S. William China and The				
Tank(s) Pumped			(COO) in the above principle	I in
Sludge and scum measured.	Liquid Level	of Tafik in. S	ludge Level in. Scum Level	in.
Do tanks need to be pumped?	Total (Ch. 4.			
Yes No (If no provide measur			uid Level = %Sludge & Scum	•
1. Access used to remove septage: Mi	aintenance Hole []Ot	her (Go to #3 below)	* Tank must be pumped if th	ic value
2. If maintenance hole was used, were all c	overs securely replaced?	Dives Tillantens	is greater than 25%.	13 ANIRE
Explanation:			E EXPIRIT	
3. If owner refuses to allow a Subsurface them complete and sign the following:	Sewage Treatment Svo	tem (SSTS) to be now.		
them complete and sign the following	statement:	rem (3313) to be pum	ped through the maintenance hole, i	lave
l,	(owner's name), refuse	to allow the removat of	solids and liquids through the mainter	
hole. I understand that removal of solids a			solids and liquids through the mainter	lance
4. Is the tank designed as a leaky tank? exam	ple: seepage pit, cesspool	drywell, leaching pit	risidered maintenance,	
Tank#1 Yes PyNo Verificatio Meth				
Tank#2 Yes No Verificatio Meth	3	×		
5. Is there evidence of tank took and from	od Used: Visua	1		•
<ol><li>is there evidence of tank leakage from a damaged, cracked, or structurally unsou</li></ol>	septic, holding, pretre ng maintenance hole c	atment or pump tank ! overs?	below the operating depth or eviden	re of
Tank	Leaking Out	Leaking In		
Septic/Holding Tank #1	Yes No	Yes Ano	Cover Damage	
Septic/Holding Tank #2	Yes ANO	Yes No	Yes Allo	
Pretreatment Tank	☐Yes ☐No	Yes No	Yes No	
Pump Tank	Yes No	Yes No	Yes Pino	
6. How many gallons of septage were remov	ed?			
Tank#3 1250 Tank#2 1000	Pretreatment Tai	nk j	Pump Tank 150	
7. Other information: List any troubleshooting	g, minor repairs condu	cted, tank safety con-	amp lank _150	
Inlet battle on TI MISSIANT	will be replaced	Y'll-	erns, or other concerns.	
Inlet battle on TI missing = 18. Certification: I hereby certify as a State of Missing and made the observations, or	innesota certified SSTS N	laintainer that I persona	not working - will be fixed	d
	and any published of the	ers in the performance o	f this job.	
Maintainer's Name: Olson's Sewer Service, In	c. Maintainer	s Address: 17638 Lyons	Street NE, Forest Lake, MN	
Maintainer's License #: 216 Maintair	ner's Phone #: 651-464-			-
Maintainer's Signature	A -	Date: /_	lanton	
7			30/23	