

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety t				
<u>prior</u> to perforr	ning maintenance activitie	es and remain on-	site for the durat	ion of the maintenar	nce activity.
Date of Maintenance:	1-4-16 Reason f	or Maintenance:	Routine		
Property Address:	1790 113th St.	> Hastings MIN	roperty Owner's N	ame: Burgnei	٢
Municipality: Denm		3 Property Iden		•	
	:20210m1014 M	— aintainer Name an	d License No. 20	989 Schlom	ka
Maintenan	ce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
XTank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	curely replaced? X Yes [of tank leakage from a sept ged, cracked, or structura	tic, holding, pretr	eatment or pump tenance hole cove	tank below the ope ers?	rating depth or
,	Tank	Leaking Out	Leaking In	Cover Damage	ř.
	Septic/Holding Tank #1	☐ Yes 🔀 No	☐ Yes 🗹 No	☐ Yes 🛣 No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
*	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?	?			
Tank #1 1500 gal Tank #2		gal Pretreatmen	tank§	gal Pump Tank	gal
5. Other information:	: List any troubleshooting,	minor repairs co	nducted, tank saf	ety concerns, or oth	er concerns.