DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730



SSTS MAINTENANCE REPORT

Date of Maintenance 8-21-17 Reason for Maintenance: Regular			
Property Address: 855 Jewel Av	e N. Prop	perty Owner's Name:	ambiz Falobakhsh
Municipality: Lake Elmo	itate MN Zip Coo	de 55042 GEO CO	ode/Property I.D. #: <u>W</u> 4533e 719
What was done to the system?	Tank Measurements (must be completed if tanks NOT pumped)		
 ☐ Tank(s) Pumped ☐ Sludge and scum measured. Do tanks need to be pumped? ☐ Yes ☐ No (If no provide measurements) 	Liquid Level of Ta		*
1. Access used to remove septage: Maintenance Hole Cother (Go to #3 below) * Tank must be pumped if this value			
is greater than 25%. 2. If maintenance hole was used, were all covers securely replaced? No please explain			
Explanation:	,		
3. If owner refuses to allow a Subsurface Sewag them complete and sign the following statem		m (SSTS) to be pumped t	hrough the maintenance hole, have
l, (owner's name), refuse to allow the removal of solids and liquids through the maintenance			
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.			
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit			
Tank#1 T Ves T/No Verificatio Method Used:			
Tank#1 Yes No Verificatio Method Used:			
Tank#2 Yes No Verificatio Method Used:			
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?			
Tank	Leaking Out	Leaking In	Cover Damage
Septic/Holding Tank #1	Yes XNo	☐ Yes 📝 No	Yes X No
Septic/Holding Tank #2	Yes IX No	☐ Yes ☐ No	☐ Yes IX No
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
Pump Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No
6. How many gallons of septage were removed?			
Tank #1 DIO Tank #2 DIO Pretreatment Tank Pump Tank			
7. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.			
8. Certification: I hereby certify as a State of Minno and made the observations, or dir			
Maintainer's Name: Olgons Scwer Maintainer's Address: 17638 Lyons 5+NE			
Maintainer's License #: 216 Maintainer's Phone #: 651464 - 2082			
Maintainer's Signature Date: 8-21-17			