

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in it	le autie t			The second second	
This section must be completed in it	is entirety to constitute a	alid maintenance	permit. This permit	must be completed	
and the perior ming maintena	nce activities and remain o	on-site for the dura	ation of the maintena	nce activity.	
Date of Maintenance:	Reason for Maintenance		tine		
Property Address: 16 80 Minos	ng Ave Sa	Property Owner's	Name: pontloi	Albera	
Municipality: Worshum		entification Numbe			
Maintenance Permit No: 90958 01					
100	Maintainer Name	and License No. Pin	ky's Environmental Se	wer Service/ L1673	
Maintenance Performed	Tank Mea	asurement (must b	e completed if tanks	NOT pumped)	
Tank(s) Pumped		Tank — in			
$\square$ Sludge and scum measured	- 11	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measu	urements) = % Sludge & So	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage:	Maintenance Hole Other	(enter authorization -	X NIBL	25% of greater	
2. Were all covers securely replaced?		dericer authorization c	ode) JU DIDTS	JANOI MENT	
<ol><li>Is there evidence of tank leakage for evidence of damaged, cracked, or</li></ol>	structurally upsound main	reatment or pump	tank below the opera	ating depth or	
	structurally unsound man	itenance note cove	ers?  Yes  No		
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Ta	nk #1 Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Ta	nk #2 ☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tan	k Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were					
Tank #1 / D D gal Tank #2 _	gal Pretreatmen	t tankg	al Pump Tank	gal	
5. Other information: List any trouble	shooting, minor repairs co	nducted, tank safe	ty concerns, or other	Concerns	
			, and a second	concerns.	
. Location of septage disposal:	STIPAN				
		Eug - Francisco V			
	Pinky's Environmental Se	ewer Service Inc.			

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673