

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	e completed in its entirety					
<u>prior</u> to perfo	orming maintenance activi	ties and remain o	n-site for the durat	ion of the maintenan	ce activity.	
Date of Maintenance:	7-5-17 Reason	n for Maintenance:	Parting			
Property Address: \(	5688 7t St. S		Property Owner's N	lame:Gn, Mo	aas	
Municipality: W					500	
	25.		entification Number			
Maintenance Permit I	No: <u>U354707128</u>	Maintainer Name a	nd License No. Pink	y's Environmental Sev	wer Service/ L1673	
Mainten	ance Performed	Tank Mea	surement (must be	completed if tanks I	NOT numped)	
Tank(s) Pumped			Liquid Level of Tank — in			
☐ Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)			= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re	move septage:   Maintena	ance Hole Other				
			enter authorization co	ode) / M S 11 /	mas copin	
	ecurely replaced? $\square$ Yes of tank leakage from a se		rootmont or nume	tank halam tha an an		
	aged, cracked, or structu				ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	1?				
Tank #1 🖊 🕰 🚱	gal Tank #2 /D>>	_gal Pretreatmen	t tankg	al Pump Tank	gal	
	: List any troubleshooting					
		The state of the s				
6. Location of septag	e disposal: 51/w					

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673