



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	WHO SEE A CONTROL OF THE PROPERTY OF THE PROPE	y to constitute a va	nd maintenance p	ermit. This permit n	nust be completed
prior to perfo	rming maintenance activi	ities and remain on	-site for the durat	ion of the maintenar	nce activity.
Date of Maintenance:	8-23-18 Reason	n for Maintenance: _	Routine	6	
	1379 Crackleby				
Municipality: ()	Oburn ZIP:551	25 Property Idea	ntification Number:	:	
Maintenance Permit N	10: <u>L2286 MS56</u>	Maintainer Name ar	nd License No. 2	989 Sch	10 MKG SOLV
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum n	neasured	Sludge Level in ⁻	Tank in	Scum Level in Tank	in
Do tanks need to		Sludge + Scum _	/ Liquid L	.evel X 100	
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater					
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2. Were all covers securely replaced? Yes No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Tank Septic/Holding Tank #1	Leaking Out			
	**************************************		Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes XNo	Leaking In Yes No	Cover Damage Yes Ano	
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐ No	Leaking In Yes No	Cover Damage Yes No	
4. How many gallons	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No	
4. How many gallons Tank #1	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	☐ Yes ☐ No ☐ d?	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal
Tank #1 1350	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	☐ Yes ☐No d? gal Pretreatment	Leaking In Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Pump Tank	
Tank #1 1350	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2	☐ Yes ☐No d? gal Pretreatment	Leaking In Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Pump Tank	
Tank #1 1350	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2	☐ Yes ☐No d? gal Pretreatment	Leaking In Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Pump Tank	