

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety to	o constitute a val	id maintenance per	mit. This permit	must be completed
prior to perfor	ming maintenance activitie	es and remain on-	site for the duratio	n of the maintena	nce activity.
Date of Maintenance:	8-24 Reason f	or Maintenance: _		·	reg. mant
Property Address:	256 113th St.	S. P	roperty Owner's Nai	me: Joseph (Chudars
Municipality: Co+	rage brown zip: 550	Property Iden	tification Number:		
Maintenance Permit No	:: 00116j8224 M	— aintainer Name an	d License No. Sc	nlomka 2	989
Maintenan	ice Performed	Tank Meas	urement (must be c	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence o	curely replaced? 🛱 Yes 🗆 If tank leakage from a sept ged, cracked, or structura	ic, holding, pretr			erating depth or
•	Tank	Leaking Out	Leaking In	Cover Damage	•:
	Septic/Holding Tank #1	☐ Yes 🍽 No	☐ Yes 风No	☐ Yes XNo	
	Septic/Holding Tank #2	☐ Yes XNo	☐ Yes ☒No	☐ Yes ☑No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	\square Yes \square No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	<u>.</u>
4. How many gallons	of septage were removed?				
Tank #1 1,000 gal Tank #2 750		gal Pretreatment	tank gal	l Pump Tank	gal
5. Other information:	List any troubleshooting,	minor repairs cor	ducted, tank safet	y concerns, or oth	er concerns.