

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a val	lid maintenance pe	ermit. This permit n	nust be complete
<u>prior</u> to perfor	ming maintenance activiti	es and remain on	-site for the durati	on of the maintenan	ce activity.
Date of Maintenance:	8-24-17 Reason	for Maintenance:	Rowline		
Property Address:	277 Crucklebur	M ALLOVE F	Property Owner's Na	ame: Piper	
11 12 12 12 12 12 12 12 12 12 12 12 12 1	Dland 710 Com	S. Dranasty Idas	atification Number		
Municipality:	Obuy ZIP: 5517 0: 58859W5760N	Property idei	itilication number.		
Maintenance Permit N	0: 58869W6/60 N	Naintainer Name ar	d License No.	2989 Schlon	The Sor/
Maintenai	nce Performed	Tank Meas	urement (must be	completed if tanks I	NOT pumped)
☑ Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum m	neasured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100					
☐ Yes ☐ No (if i	no provide measurements)	= % Sludge & Scu	ım Tar	iks must be pumped i	if 25% or greater
1. Access used to rem	nove septage: 🗆 Maintenar	nce Hole 🗌 Other (e	enter authorization co	ode) Dre 80	
2. Were all covers see	curely replaced? 🖄 Yes	□No	28		
	of tank leakage from a sep ged, cracked, or structura				ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🖾 No	☐ Yes No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank			16.000 No.000	
		☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons		☐ Yes ☐ No			
CAN MINAMENTAL CONTRACTOR TO STATE OF S	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	gal
Tank #1 1500	Pump Tank of septage were removed	☐ Yes ☐ No Pretreatment	☐ Yes ☐ No	Yes No	
Tank #1 1500	Pump Tank of septage were removed gal Tank #2	☐ Yes ☐ No Pretreatment	☐ Yes ☐ No	Yes No	
Tank #1 1500	Pump Tank of septage were removed gal Tank #2	☐ Yes ☐ No Pretreatment	☐ Yes ☐ No	Yes No	