


## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER





## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to perform	ming maintenance activition	es and remain on-	site for the dura		
Date of Maintenance: 8-25 Reason for Maintenance: 101 Mant.					
Property Address: 9383 Jane Cir Property Owner's Name: Arry Oigh					
	e Elmo zip: SSOL			•	
NACIONAL DE SECONOMINA	:H385745763 M			31477 NO. 7740	
Maintenan	ce Performed	Tank Meas	urement (must b	e completed if tanks N	OT pumped)
⊠ Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ol> <li>Were all covers sec</li> <li>Is there evidence or</li> </ol>	ove septage: Maintenan urely replaced? 'Yes f tank leakage from a sept ged, cracked, or structura	□ No cic, holding, pretr	eatment or pump	tank below the opera	iting depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
-	Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
× _	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of	of septage were removed?				
Tank #1 1500 gal Tank #2		gal Pretreatment tankga		gal Pump Tank	gal
5. Other information:	List any troubleshooting,	minor repairs cor	iducted, tank saf	ety concerns, or other	concerns.