

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a val	id maintenance pe	ermit. This permit n	nust be completed
<u>prior</u> to perfor	ming maintenance activi	ties and remain on	site for the durati	on of the maintenar	ice activity.
	8-18-17 Reason				
Property Address:	10720 Manning	trict N F	roperty Owner's Na	ame: LoFboor	η
Municipality:	11 Water ZIP: 55	32 Property Ider	tification Number:	-	
Maintenance Permit N	o: <u>I 88594574</u>	Maintainer Name ar	d License No	989 Schlom	ke serv
Maintenai	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum m	neasured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100					
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater					
1. Access used to rem	nove septage: Maintena	ance Hole 🗆 Other (e	enter authorization co	ode)	
2. Were all covers see	curely replaced? 🏿 Yes	□No			
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes 🗖 No	☐ Yes ☐No	
	Septic/Holding Tank #2				
	soprio,	☐ Yes ☐ No	☐ Yes ⊠No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	70 C N N N N N N N N N N N N N N N N N N	•)	
4. How many gallons	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No	gal
Tank #1 \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Pretreatment Tank Pump Tank of septage were removed	Yes No Yes No d? gal Pretreatmen	☐ Yes ☐ No ☐ Yes ☐ No t tankg	Yes No Yes No al Pump Tank	
Tank #1 \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Yes No Yes No d? gal Pretreatmen	☐ Yes ☐ No ☐ Yes ☐ No t tankg	Yes No Yes No al Pump Tank	