

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance;	/()-20-17 Reason	for Maintenance: _	Reg Ma	dif		
Property Address:	640 Olinda +	<u> </u>	roperty Owner's Na	ame: <u>Deboc</u>	South	
Municipality: Mari	ne zipiss	047 Property Iden	tification Number:			
Maintenance Permit No	27817×9406			e's Sewer Service/L	2428	
,,,amesianos , sinite i i						
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
☐ Tank(s) Pumped ☐ Sludge and scum measured ☐ Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements)		Il '	Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater				
		1. Access used to rem	ove septage: 🖒 Mainten	ance Hole 🗌 Other (e	nter authorization co	ode)
3. Is there evidence of	curely replaced? Tes of tank leakage from a se ged, cracked, or structu	ptic, holding, pretr	eatment or pump tenance hole cove	tank below the ope	rating depth or	
evidence of dame	ged, clacked, or structu	cuty and and		- L 103 = 110		
evidence of dama	Tank	Leaking Out	Leaking In	Cover Damage		
evidence of dama				<del></del> 1		
evidence of dama	Tank	Leaking Out	Leaking In	Cover Damage		
evidence of dama	Tank Septic/Holding Tank #1	Leaking Out  Yes Ano	Leaking In	Cover Damage  Yes 140		
evidence of dama	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out  Yes Ano Yes Tho	Leaking In  ☐ Yes ☐ No  ☐ Yes ☐ No	Cover Damage  Yes No		
evidence of dama	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out  Yes Ano Yes Ano Yes No	Leaking In  Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No		
4. How many gallons Tank #1	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank  of septage were remove	Leaking Out  Yes ANO Yes No Yes ANO Yes ANO	Leaking In  Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No	gal	
4. How many gallons Tank #1	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank  of septage were remove	Leaking Out  Yes ANO Yes No Yes ANO Yes ANO	Leaking In  Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No	gal er concerns.	
4. How many gallons Tank #1	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank  of septage were remove	Leaking Out  Yes ANO Yes No Yes ANO Yes ANO	Leaking In  Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No	gal per concerns.	
4. How many gallons Tank #1	Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  of septage were remove  gat Tank #2  List any troubleshootin	Leaking Out  Yes ANO Yes No Yes ANO Yes ANO	Leaking In  Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No	gal per concerns.	

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934