

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: $5/8/17$ Reason f	or Maintenance:	ROUTINE		
Property Address: 13:169 60th St		1980	lame: TIM BL	TRILIAM
				DAGUIOI
		ntification Number		
Maintenance Permit No: <u>C78 70 o 5960</u> M.	aintainer Name ar	nd License No. <u>Mey</u>	er Sewer Service, Inc	c./L915
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of Tank in			
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid I = % Sludge & Scum Ta		Level X 100 anks must be pumped if 25% or greater	
$\square$ Yes $\square$ No (if no provide measurements)				
1. Access used to remove septage:   Maintenance	ce Hole X Other (e	enter authorization co	ode)	
2. Were all covers securely replaced? ☐ Yes ☐			· · · · · · ·	
		eatment or numn	tank bolow the one	erating donth or
3. Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structural	lly unsound main	tenance hole cove	ers?	eracing depth of
	COR 51 08 000 051			1
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Ductus star and Tauli				
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No	
Pump Tank				
Pump Tank  4. How many gallons of septage were removed?	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	gal
Pump Tank  4. How many gallons of septage were removed?  Tank #1 1500 gal Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank  4. How many gallons of septage were removed?  Tank #1 gal Tank #2  5. Other information: List any troubleshooting,	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank  4. How many gallons of septage were removed?  Tank #1 1500 gal Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162

Maintenance activities must be reported to the Department within 90 days.