

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	to constitute a ra	nd manitenance p	ermit. This permit r	nust be complete
prior to performing maintenance activiti	ies and remain on	-site for the durat	ion of the maintenar	nce activity.
Date of Maintenance: 6/1//7 Reason	for Maintenance:	Routine)	0
Property Address: 8236 1/3 to St	.S. F	Property Owner's N	ame: Steve	Brutton
Municipality: Cattaca HaneZIP: 550	OW Proporty Idor	atification Number	, , , , , ,	,
Maintenance Permit No: 1848226483N	laintainer Name ar	d License No		
			Assert Shirthead San Silver	
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
✓ Tank(s) Pumped	Liquid Level of 7	ank in		
Sludge and scum measured	Sludge Level in ⁻	Γank in	Scum Level in Tank	in
Do tanks need to be pumped?	Sludge + Scum _	/ Liquid L	evel X 100	
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintenar	nce Hole 🗌 Other (e	enter authorization co	ode)	
2. Were all covers securely replaced? Z Yes			(
3. Is there evidence of tank leakage from a sep		estment or numn	AND THE RESIDENCE OF THE PARTY	
evidence of damaged, cracked, or structura				rating depth or
				rating depth or
evidence of damaged, cracked, or structura	ally unsound main	Leaking In	rs?	rating depth or
evidence of damaged, cracked, or structura Tank	Leaking Out	Leaking In	Cover Damage Ves No	rating depth or
evidence of damaged, cracked, or structura Tank Septic/Holding Tank #1	Leaking Out Yes No	Leaking In Yes No	Cover Damage Ves No	rating depth or
evidence of damaged, cracked, or structura Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No	Leaking In Yes No	Cover Damage Yes No Yes No	rating depth or
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No	Cover Damage Yes No Yes No Yes No	rating depth or
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed:	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal
evidence of damaged, cracked, or structura Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed: Tank #1 /250 gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed: Tank #1 /250 gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal