

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance	permit. This permit n	nust be completed
<u>prior</u> to perfor	ming maintenance activit	ies and remain on	-site for the dura	ation of the maintenar	nce activity.
Date of Maintenance:	6/1/17 Reason	for Maintenance:	Routine)	
Property Address:	290 Morell	aven 1	Property Owner's	Name: Gled On	ustigian)
Municipality: Wast	Lakeland ZIP: 550	V*		6: 1	
Maintenance Permit N	0: <u>55287w6482</u> N	Maintainer Name ar	nd License No/	neyer- L9	15
Maintena	nce Performed	Tank Meas	urement (must b	oe completed if tanks I	NOT pumped)
$oldsymbol{Z}$ Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum m	neasured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100					
☐ Yes ☐ No (if	no provide measurements)	H		anks must be pumped i	if 25% or greater
2. Were all covers see3. Is there evidence of	nove septage: Maintenal curely replaced? Yes of tank leakage from a sep aged, cracked, or structure	□ No tic, holding, pretr	eatment or pum	p tank below the oper	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑No	☐ Yes 🗐 No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	\square Yes \square No	\square Yes \square No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
	Tank #1 1200 gal Tank #2		gal Pretreatment tank		
Tank #1 1200) gal Tank #2	gal Pretreatment	t tank	gal Pump Tank	gal
1000	gal Tank #2 List any troubleshooting,	- `			
1000	-	- `			
1000	-	- `			