

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| This section must be | completed in its entirety | to constitute a va | lid maintenance p | ermit. This permit i | must be completed | |
|--|---|--|---|-----------------------|-------------------|--|
| <u>prior</u> to perfo | rming maintenance activi | ties and remain on | -site for the durat | ion of the maintena | nce activity. | |
| Date of Maintenance: | 6/1/17 Reason | for Maintenance: | Routine | | | |
| Property Address: 🥳 | 305 Centure | wes. | Property Owner's N | lame: Bill (| allen) | |
| 0.1 | odbury ZIP: 55 | <i>X</i> | | | | |
| Maintenance Permit N | 10: 17540g6481 | Maintainer Name ar | nd License No/ | MEYER-L | 915 | |
| Maintena | nce Performed | Tank Meas | urement (must be | completed if tanks | NOT pumped) | |
| Tank(s) Pumped | | Liquid Level of | Liquid Level of Tank in | | | |
| Sludge and scum n | neasured | Sludge Level in | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100 | | | | | | |
| ☐ Yes ☐ No (if | = % Sludge & Sco | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | | |
| 2. Were all covers se3. Is there evidence | nove septage: Maintena curely replaced? Yes of tank leakage from a se aged, cracked, or structur | □ No ptic, holding, preti | eatment or pump | tank below the ope | rating depth or | |
| | Tank | Leaking Out | Leaking In | Cover Damage | | |
| | Septic/Holding Tank #1 | ☐ Yes ☐ No | ☐ Yes Z No | ☐ Yes ☐No | | |
| | Septic/Holding Tank #2 | ☐ Yes 🛮 No | ☐ Yes 🗖 No | ☐ Yes ☐ No | | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes 🗖 No | ☐ Yes 🗷 No | | |
| 4. How many gallons | of septage were removed | 1? | | al e | | |
| Tank #1 / りもひ | gal Tank #2 1000 | _gal Pretreatmen | t tankg | al Pump Tank /W | gal | |
| 5. Other information | : List any troubleshooting | g, minor repairs co | nducted, tank safe | ety concerns, or othe | er concerns. | |
| | | | | | | |
| an A | 2 | | www.museurin | | | |
| 6. Location of septage | 222 228 | | | | | |