

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be complete						
<u>prior</u> to perfor	ming maintenance activi	ties and remain on	-site for the durati	on of the maintenar	ice activity.	
Date of Maintenance:	6/2/2017 Reason	for Maintenance:	Routine			
Date of Maintenance:	6/0/00// Redsoi	n for Maintenance.	rounce	4.	9 ./	
Property Address: //	Quinlan Ch	RJ.	Property Owner's N	ame: The D	expert	
Municipality: Labor	land Shoreszip: 550	142 Property Ide	ntification Number:	,	0	
Maintenance Permit N	o: <u>C217906486</u>	Maintainer Name ar	id License No.	1848K-19	75	
				Anagaraja sa pagaman		
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum m	neasured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if	= % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to ren	nove septage: 🗌 Maintena	ince Hole Other (e	enter authorization co	ode)		
2. Were all covers securely replaced? ☐ Yes ☐ No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ☐No	☐ Yes ☐ No		
		•				
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No		
4. How many gallons	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
The second secon	Pretreatment Tank Pump Tank	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	gal	
Tank #1 1200	Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ Ro ☐ gal Pretreatmen	☐ Yes ☐ No ☐ Yes ☐ No t tankg	☐ Yes ☐ No ☐ Yes ☐ No al Pump Tank		
Tank #1 1200 5. Other information	Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Yes No Yes No Yes No gal Pretreatments, minor repairs co	☐ Yes ☐ No ☐ Yes ☐ No t tankganducted, tank safe	☐ Yes ☐ No ☐ Yes ☐ No al Pump Tank		
Tank #1 1200 5. Other information	Pretreatment Tank Pump Tank of septage were removed gal Tank #2 List any troubleshooting	Yes No Yes No Yes No gal Pretreatments, minor repairs co	☐ Yes ☐ No ☐ Yes ☐ No t tankganducted, tank safe	☐ Yes ☐ No ☐ Yes ☐ No al Pump Tank		
Tank #1 1200 5. Other information	Pretreatment Tank Pump Tank of septage were removed gal Tank #2 : List any troubleshooting	Yes No Yes No Yes No gal Pretreatments, minor repairs co	☐ Yes ☐ No ☐ Yes ☐ No t tankganducted, tank safe	☐ Yes ☐ No ☐ Yes ☐ No al Pump Tank		