

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be complete					
<u>prior</u> to perfor	ming maintenance activiti	es and remain on	-site for the durati	on of the maintenan	ce activity.
Date of Maintenance: 6/5/17 Reason for Maintenance: Routine					
Property Address: 80	33 Quadra	nt ave. S. F	Property Owner's Na	ame: Doug	Schaffer
Municipality: Denn	nark ZIP: 550:	33 Property Ide	ntification Number:	0-	00
	: a3725K6490 M				15
Maintenance Permit No	. W Tasket ic M	amtamer Name ar	id Electise No. 1	- YEK- 11	J
Maintenan	ce Performed	Tank Meas	urement (must be	completed if tanks I	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage: 🂢 Maintenan	ce Hole 🗌 Other (6	enter authorization co	de)	
2. Were all covers securely replaced? 💢 Yes 🗆 No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 💢 No	☐ Yes 💢No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes 风No	☐ Yes 🇷 No	☐ Yes ☑ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
ti	Pretreatment Tank Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons o		☐ Yes ☐ No			
	Pump Tank of septage were removed?	☐ Yes ☐ No		☐ Yes ☐ No	gal
Tank #1 1250	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 1250	Pump Tank of septage were removed? gal Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 1250	Pump Tank of septage were removed? gal Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	