

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.						
Date of Maintenance: 6/6/17 Reason for Maintenance: <u>Routine</u>						
Property Address: 162 Quehl aven. Property Owner's Name: Juston						
	,			// //	,	
Municipality: <u>Jakoland</u> ZIP: <u>55043</u> Property Identification Number:						
Maintenance Permit N	o: <u>X2427K6493</u> M	Maintainer Name ar	d License No. <u>M</u>	EYER- L91)	
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum m	neasured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100						
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater					if 25% or greater	
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)						
2. Were all covers securely replaced? Yes No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes 🗹 No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?						
Tank #1 1750	gal Tank #2	gal Pretreatmen	t tank g	al Pump Tank	gal	
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
Manhole under dock Past.						
6. Location of septage	e disposal:					