

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	6/8/17 Reason f	for Maintenance:	Routine		8
Property Address: 21 Quanwell ave & Property Owner's Name: Patricia Fore					
Municipality: Lakeland ZIP: 55043 Property Identification Number:					
Maintenance Permit No: 1369816501 Maintainer Name and License No. Meyer Sewer Service, Inc./L915					
mantenance remit is		ame name a	ia Electise No. Meye	er sewer service, in	2.7 2.713
		Tromanae — aar var verbe			
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (1f i					
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2. Were all covers securely replaced? Yes No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
evidence of damaged, cracked, or structurally unsound maintenance note covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
*	Septic/Holding Tank #1	☐ Yes ☑No	□ Yes 🗖 No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ⊅ No	□ Yes ⊅ No	☐ Yes ☐ No	
-	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 <u>/ 00 0</u> gal Tank #2 <u>/ 000</u> gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
Tanks have Lanscape Timbers over them Purpel Hong yinchpyon					
6. Location of septage disposal:					

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162