

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	11.21.7		Poutino	) (								
Date of Maintenance: _	6/13/17 Reason	for Maintenance: _	Moure	0.0	• /							
Property Address: 13	260 5/3/St	.91, P	operty Owner's Na	me: Joe Cu	(sick)							
Municipality: Bay	town ZIP: 550	${\cal B}{\cal Q}$ Property Iden	tification Number:									
Maintenance Permit No	:C178066519 N	Naintainer Name an	d License No. <u>Meye</u>	r Sewer Service, Inc	./L915							
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)										
☐ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped?		Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater										
						$\square$ Yes $\square$ No (if no provide measurements)		70 Staage a see	- % studge a scani			
						1. Access used to rem	ove septage: Maintena	nce Hole 🗌 Other (e	nter authorization co	de)		
2. Were all covers sec	curely replaced?  Yes	□No										
3. Is there evidence of	f tank leakage from a sep ged, cracked, or structur	otic, holding, pretr	eatment or pump	tank below the ope	rating depth or							
evidence of dama	ged, cracked, or structur	ally unsound main	teriance note cove	131	-							
	Tank	Leaking Out	Leaking In	Cover Damage								
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ☐No	☐ Yes ☐No								
	Septic/Holding Tank #2	☐ Yes ☐ No	$\square$ Yes $\square$ No	☐ Yes ☐ No								
	725a 277 807 200 200 200 200 200 200 200 200 200 2		2008	W-12								
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No								
	Pretreatment Tank Pump Tank	☐ Yes ☐ No☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No☐ Yes ☐ No								
	Pump Tank	☐ Yes ☐ No										
4. How many gallons	Pump Tank  of septage were removed	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	gal							
Tank #1 /500	Pump Tank  of septage were removed gal Tank #2	☐ Yes ☐ No  I? _ gal Pretreatmen	☐ Yes ☐ No	☐ Yes ☐ No al Pump Tank	gal ner concerns.							
Tank #1 <u>/500</u> 5. Other information:	Pump Tank  of septage were removed gal Tank #2 : List any troubleshooting	Yes No  Yes No  Repair Pretreatments, minor repairs co	☐ Yes ☐ No	☐ Yes ☐ No al Pump Tank	gal ner concerns.							
Tank #1 <u>/500</u> 5. Other information:	Pump Tank  of septage were removed  gal Tank #2  : List any troubleshooting  ED River & Cor	Yes No  Yes No  Representation of the second	☐ Yes ☐ No t tank g nducted, tank safe	☐ Yes ☐ No al Pump Tank	gal ner concerns.							
Tank #1 <u>/500</u> 5. Other information:	Pump Tank  of septage were removed  gal Tank #2  : List any troubleshooting  ED River & Cor	Yes No  Yes No  Repair Pretreatments, minor repairs co	☐ Yes ☐ No t tank g nducted, tank safe	☐ Yes ☐ No al Pump Tank	gal ner concerns.							

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001

License# 915 P: 651-459-0162