

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	0/19/17 Reason	for Maintenance: _	Routine)			
Property Address: 150	30 /13th	St St. n. F	Property Owner's N	ame: Bernie	Zeruhn	
Municipality: Stillwa						
Maintenance Permit No: $\chi$				er Sewer Service, Inc	 :./L915	
maintenance reminerior <u>.y.</u>	, , , , , , , , , , , , , , , , , , , ,			,		
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100   = % Sludge & Scum Tanks must be pumped if 25% or greater				
☐ Yes ☐ No (if no provide measurements)		Notice Section	- 70 Studge & Seam Tanks mase be pumped in 25% of greater			
1. Access used to remove	septage: Maintena	ance Hole $\square$ Other (6	enter authorization co	ode)		
2. Were all covers secure	ly replaced? Yes	□No				
3. Is there evidence of tar evidence of damaged,			eatment or pump	tank below the ope	erating depth or	
evidence of damaged,	cracked, or structur	rally unsound main	tenance hole cove	rs?		
Parameter 1	Control of the contro					
	Tank	Leaking Out	Leaking In	Cover Damage		
Sep	Tank tic/Holding Tank #1	Leaking Out	Leaking In  Ves No	Cover Damage  Ves No		
5.55	ENGRANDAS					
Sep	tic/Holding Tank #1	☐ Yes 🛮 No	☐ Yes No	☐ Yes ☐No		
Sep Pret	tic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑ No ☐ Yes ☑ No	☐ Yes ☐ No☐ Yes ☐ No		
Sep Pret Pun  4. How many gallons of se Tank #1	tic/Holding Tank #1 tic/Holding Tank #2 treatment Tank np Tank eptage were removed I Tank #2	Yes No Yes No Yes No Yes No	Yes No Yes No Yes No Yes No	☐ Yes ☐ No		
Sep Pret Pun  4. How many gallons of se	tic/Holding Tank #1 tic/Holding Tank #2 treatment Tank np Tank eptage were removed I Tank #2	Yes No Yes No Yes No Yes No	Yes No Yes No Yes No Yes No	☐ Yes ☐ No		
Sep Pret Pun  4. How many gallons of se Tank #1	tic/Holding Tank #1 tic/Holding Tank #2 treatment Tank np Tank eptage were removed I Tank #2	Yes No Yes No Yes No Yes No	Yes No Yes No Yes No Yes No	☐ Yes ☐ No		

Meyer Sewer Service, Inc. 5325 Manning Ave S Afton, MN 55001 License# 915 P: 651-459-0162