

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	6/29/17 Reason	for Maintenance: _	Routin	L							
Property Address: _//	240 Kingolvoro	ugh Is. P	roperty Owner's N	ame: Mya L	ee						
Municipality: Cutta	ger from ZIP: 550	Property Ider	ntification Number:	10							
	0:p3012 y 6894 M				c./L915						
manrechance remiters	0.500127007	amen name a	.a								
					VOT						
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)									
<ul> <li>☐ Tank(s) Pumped</li> <li>☐ Sludge and scum measured</li> <li>Do tanks need to be pumped?</li> <li>☐ Yes ☐ No (if no provide measurements)</li> </ul>		Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater									
						1. Access used to remove septage:   Maintenance Hole Other (enter authorization code)					
						2. Were all covers securely replaced?  Yes No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?											
	Tank	Leaking Out	Leaking In	Cover Damage	]						
	Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes 🗹 No	☐ Yes ☐ No	]						
	Septic/Holding Tank #2	☐ Yes ☑No	☐ Yes ☐ No	☐ Yes ☐ No							
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No							
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	]						
8 W21 3 W 3 C											
4. How many gallons of septage were removed?  Tank #1 \( \sumeq OOO \) gal Tank #2 \( \sumeq OOO \) gal Pretreatment tank gal Pump Tank gal											
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.											
pupel through b" piped lacks in Languaging wall and pavers over											
project of	will b grant	jacks jac	Dilling Control		Tals						
6. Location of septage disposal:											

Meyer Sewer Service, Inc.
5325 Manning Ave S
Afton, MN 55001
License# 915 P: 651-459-0162