

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	Reaso	n for Maintenance: _	Key M	arla for	<del></del>	
Property Address: 2	328 Neal Au	<u>e //</u>	Property Owner's N	ame: <u>//av-y</u>	Petrisko	
Municipality: <u>5/7//</u>	water zie:550	Property Ide	ntification Number:	:		
Maintenance Permit No	o:	Maintainer Name ar	nd License No. <u>Smil</u>	<u>ie's Sewer Service/L</u>	2428	
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
☐ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped?		11 '	Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
		= % Sludge & Scu				
☐ Yes ☐ No (if i	no provide measurements	5)				
1. Access used to rem	nove septage: Mainten	nance Hole 🗆 Other (e	enter authorization co	ode)		
<ul> <li>2. Were all covers securely replaced?  Securely replaced.  Securely replaced?  Securely replaced.  Securely replaced.</li></ul>						
	<del>-</del>					
	<del>-</del>				]	
	ged, cracked, or structu	irally unsound main	tenance hole cove	rs? 🗌 Yes 🖾 No		
	ged, cracked, or structu Tank	Leaking Out	tenance hole cove	Cover Damage		
	ged, cracked, or structu Tank Septic/Holding Tank #1	Leaking Out  Yes 4No	Leaking In  Yes Ato	Cover Damage  Yes No	·	
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out  Yes 4No  Yes No	Leaking in  Yes No	Cover Damage  Yes No  Yes No		

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934