

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: _	10-9-17 Reason	for Maintenance:	Keg Ma	in		
Property Address: 23	90 20 Znd	ST // P	roperty Owner's Na	ame: Donna	Schippen	
Municipality: Tree	2 / 1 - TT	Property Ider			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Maintenance Permit No	1251 5327	<u> </u>		e's Sewer Service/Li	 2428	
Maintenance Fermit No	5. <u>1005/1007 8</u>	manitaniei name an	d License No. Since	<u>e a serrer serrice, e</u>		
	Singayoranga asang kang aban ing ng sakarang					
Maintenance Performed Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped?		Tank Measurement (must be completed if tanks NOT pumped) Liquid Level of Tank in				
						11 -
		= % Sludge & Scu				
		☐ Yes ☐ No (if r	no provide measurements)	·		
1. Access used to rem	nove septage: 🗖 Maintena	ance Hole \square Other (e	enter authorization co	ode)		
2. Were all covers sec	curely replaced? Yes	□ No ptic, holding, pretr	eatment or pump	tank below the ope	rating depth or	
		rally unsound main	tenance hole cove			
	ged, cracked, or structu	rally unsound main Leaking Out	tenance hole cove Leaking In			
	ged, cracked, or structu			rs? 🗌 Yes 🗖 🔨	ı.	
	ged, cracked, or structu	Leaking Out	Leaking In	rs?		
	ged, cracked, or structure Tank Septic/Holding Tank #1	Leaking Out ☐ Yes ②No	Leaking In	Cover Damage Yes CNO		
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out ☐ Yes ☐ No ☐ Yes ☐ No	Leaking In Yes Avo	rs? ☐ Yes ☐ No Cover Damage ☐ Yes ☐ No ☐ Yes ☐ No	·	
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No	Leaking In Yes TNO Yes No Yes No	Cover Damage Yes ONO Yes No Yes No	•	
4. How many gallons- Tank #1	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	rs?	gal	
4. How many gallons- Tank #1	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	rs?	gal	
4. How many gallons- Tank #1	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2 List any troubleshooting	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	rs?	gal	

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934