C 78298827



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	e completed in its entirety	y to constitute a va	alid maintenance	permit. This permit m	oust be completed	
<u>prior</u> to perfo	orming maintenance activi	ties and remain or	n-site for the dur	ation of the maintenan	ce activity.	
Date of Maintenance:	: <u>9-14-17</u> Reason	n for Maintenance:				
Property Address:	3785 274 S	t. N	Property Owner's	Name: Scott Dy	en	
	Clmo ZIP:			,		
Maintenance Permit I	No: <u>C7829s8276</u>	Maintainer Name a	nd License No	2989		
William	JudovPergrennieg	Tank Mea	surement (must l	percomplete efficialis	(Olifoninies)	
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
$ec{\Box}$ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence	ecurely replaced? 🔀 Yes of tank leakage from a se aged, cracked, or structur	ptic, holding, pret	reatment or pum Itenance hole co	p tank below the opera vers?	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	□ Yes 🎾 No	☐ Yes ☑No	☐ Yes 🗖 No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	l?		-		
Tank #1 1,750 gal Tank #2		gal Pretreatmen	t tank	gal Pump Tank	gal	
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank sa	fety concerns, or other	concerns.	