

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730



## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.						
Date of Maintenance:	<u>9/18/7</u> Reason	for Maintenance:	ROUTINE			
Property Address: 418 WOLDLANDE Property Owner's Name: JOHN DEAN						
Municipality: レなんイ ZIP: Property Identification Number:						
Maintenance Permit N	0: 47690 J 8274	Maintainer Name ar	nd License No	2981		
/Mathiteina	nge Renignmed	Tank Meas	urement (must be	completed fistaniks	(कार विभागवान्त्रको)	
Tank(s) Pumped		Liquid Level of	Liquid Level of Tank in			
Sludge and scum measured Sludge Level in Tank in Scum Level in Tank in						
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100						
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & Sci	um Ta	nks must be pumped	if 25% or greater	
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)						
2. Were all covers securely replaced?  \( \sum \text{Yes} \sum \text{No} \)						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🗖 No	☐ Yes 🖄 No	☐ Yes√Z No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?				
Tank #1 1500 gal Tank #2 g		gal Pretreatment tankgal		al Pump Tank	gal	
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·			<u>.</u>	
· 	·				·	
6. Location of septage disposal: ハステスタ アレルマ						