

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	11-6-17 Reason	for Maintenance: _	La Mai	67		
Property Address: 19	241 Orwell A	tve // P	roperty Owner's N	ame: Far I	Trickson	
Municipality: Mar	ine zip:550	247 Property Ider				
Maintenance Permit No		•		ie's Sewer Service/L	.2428	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
☐ Tank(s) Pumped☐ Sludge and scum measured		II .	Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
		_				
Do tanks need to be pumped?		= % Sludge & Scu				
	no provide measurements)	)				
1. Access used to rem	nove septage: 🖒 Maintena	ance Hole $\Box$ Other (e	nter authorization co	ode)		
<ul> <li>2. Were all covers securely replaced?  See No</li> <li>3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?  Yes  No</li> </ul>						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ☐No	☐ Yes 🗖 No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	$\square$ Yes $\square$ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes 🗖 No	☐ Yes [] No		
Tank #1	of septage were removed gal Tank #2 List any troubleshooting	_ gal Pretreatment				

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934