

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	Reason	for Maintenance:	RES MI	613							
Property Address:	7870 200	195/ N/ F	roperty Owner's N	ame: Kugev	Kunze						
Municipality: 7000	17 / t ZIP: 550	Property Ider	ntification Number:								
Maintenance Permit N	o: 1 <i>4193529505</i> 1	Maintainer Name ar	nd License No. Smil	ie's Sewer Service/L2	2428						
	<u> </u>										
Maintenance Performed Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped?		Tank Measurement (must be completed if tanks NOT pumped)									
		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater									
						☐ Yes ☐ No (if i	no provide measurements)				
						1. Access used to ren	nove septage: 🗖 Maintena	nce Hole 🗌 Other (e	enter authorization co	ode)	
3. Is there evidence of	curely replaced? Ves of tank leakage from a sep	otic, holding, pretr			rating depth or						
evidence of damaged, cracked, or structurally unsound maintenance hole covers? 🔲 Yes 🗵 Ho											
evidence of dame	god, tradite, or bridge			100 42 110							
cyldenee of dame	Tank	Leaking Out	Leaking In	Cover Damage							
evidence of dame	· · · · · · · · · · · · · · · · · · ·				•						
evidence of dame	Tank	Leaking Out	Leaking In	Cover Damage							
evidence of dame	Tank Septic/Holding Tank #1	Leaking Out	Leaking In	Cover Damage Ves ANO							
evidence of dame	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No	Leaking In Yes And Yes No	Cover Damage Yes Ato Yes No							
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No	Leaking In Yes And Yes No Yes No	Cover Damage Yes No Yes No							
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Leaking Out Yes Mo Yes No Yes No Yes No	Leaking In Yes Ano Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal						
4. How many gallons Tank #1 / 00	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Leaking Out Yes Mo Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes Ato Yes No Yes No Yes No Pes No							
4. How many gallons Tank #1 / 00	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Leaking Out Yes Mo Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes Ato Yes No Yes No Yes No Pes No							
4. How many gallons Tank #1 / 00	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2 List any troubleshooting	Leaking Out Yes Mo Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes Ato Yes No Yes No Yes No Pes No							

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934