

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	10/4/17 Reason	for Maintenance:	POUTING								
	16 ST CROIX S			me: follo V	WILLOCK						
	LINAL (ZIP: 55										
Maintenance Permit No	:0428e8906	—– Maintainer Name an	d License No. Smili	e's Sewer Service/L	2428						
Manreenands I brown	-				· · · · · · · · · · · · · · · · · · ·						
Maintenan	ce Performed	Tank Measi	irement (must be	completed if tanks	NOT pumped)						
★ Tank(s) Pumped □ Sludge and scum measured Do tanks need to be pumped?		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater									
						☐ Yes ☐ No (if n	o provide measurements))	·		
						1. Access used to rem	ove septage: 🏿 Maintena	ance Hole 🗌 Other (e	nter authorization co	ode)	
 Were all covers securely replaced? Yes \(\sumsymbol{\text{No}} \) No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? \(\sumsymbol{\text{Yes}} \) Yes \(\sumsymbol{\text{No}} \) 											
CTICCHEC OF CO	sea, cracker, or or an arm	•		•							
CYTACTICS OF SUMME	Tank	Leaking Out	Leaking In	Cover Damage							
evidence of dame											
Cylddiles of same	Tank	Leaking Out	Leaking In	Cover Damage							
CYICGIICO DI GANTA	Tank Septic/Holding Tank #1	Leaking Out ☐ Yes 🎮 No	Leaking In	Cover Damage Yes No							
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No Yes No	Leaking In Yes No Yes No	Cover Damage Yes No Yes No							
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out ☐ Yes ANO ☐ Yes ☐ No ☐ Yes ☐ No	Leaking In ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	Cover Damage Yes No Yes No Yes No							
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2	Leaking Out ☐ Yes ANO ☐ Yes ☐ NO	Leaking In Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal						
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	Leaking Out ☐ Yes ANO ☐ Yes ☐ NO	Leaking In Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal ner concerns.						
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2	Leaking Out ☐ Yes ANO ☐ Yes ☐ NO	Leaking In Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal her concerns.						
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2 List any troubleshootin	Leaking Out ☐ Yes ANO ☐ Yes ☐ NO	Leaking In Yes No Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal her concerns.						

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073 License# 2428 P: 651-433-3934