

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance	7-22-17 Reason	for Maintenance:	Kea Main			
_		Tal () P	roperty Owner's Na	me: Pape For	le novisec	
Property Address: 2	Ti rec	·		, p		
Municipality: <u>Cand</u>			tification Number:			
Maintenance Permit No	: <u>90135a200</u> 1	Maintainer Name an	d License No. <u>Smili</u>	e's Sewer Service/L	2428	
/ Maintenan	ce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(a) Rumped		Liquid Level of T	Liquid Level of Tank in			
Tank(s) Pumped		Sludge Level in 1	Sludge Level in Tank in Scum Level in Tank in			
☐ Sludge and scum measured Do tanks need to be pumped?		-	Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if no provide measurements)		= % Studge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage: Maintena	ance Hole 🗀 Other (e	enter authorization co	ide)		
2. Were all covers securely replaced? Ves No						
Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth of						
	· ·					
evidence of dama	ged, cracked, or structu	rally unsound main	tenance hole cove	rs? 🗌 Yes 🗓 Ko	•	
evidence of dama	ged, cracked, or structur	rally unsound main Leaking Out	tenance hole cove	rs?		
evidence of dama	ged, cracked, or structu	rally unsound main	tenance hole cove	rs? Yes UNO 		
evidence of dama	ged, cracked, or structur	Leaking Out	Leaking In	Cover Damage		
evidence of dama	Tank Septic/Holding Tank #1	Leaking Out Yes [2] No	Leaking In Yes ONo	Cover Damage Yes Ano		
evidence of dama	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No	Leaking In Yes No Yes No	Cover Damage Yes Ano Yes Ano		
evidence of dama	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No	Leaking In Yes No Yes No	Cover Damage Yes Alo Yes Alo Yes Alo Yes Alo		
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	Leaking Out Yes No Yes No Yes No Yes No Yes No Res No Res No Res No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes Ano Yes Ano Yes No Yes No Yes No	IO gal	
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	Leaking Out Yes No Yes No Yes No Yes No Yes No Res No Res No Res No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes Ano Yes Ano Yes No Yes No Yes No	IO gal	
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	Leaking Out Yes No Yes No Yes No Yes No Yes No Res No Res No Res No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes Ano Yes Ano Yes No Yes No Yes No	IO gal	

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934