

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: 6/19/17 Reason for Maintenance: Koutine					
Property Address: 12623 HomeStead Dr. Property Owner's Name: Jim Laumer					
Municipality: 4uao ziP: 65038 Property Identification Number:					
Maintenance Permit No: Q 48 33 5 7551 Maintainer Name and License No. Smilie's Sewer Service/L2428					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in Sludge Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if no provide measurements)		, stage a sam rame mase se pampa in 1970 or greater			
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)					
2. Were all covers securely replaced? 🔼 Yes 🗆 No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or					
evidence of damaged, cracked, or structurally unsound maintenance hole covers? Yes No					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	□ Yes 🕬 No	☐ Yes 🎞 No	☐ Yes 🕬 No	
	Septic/Holding Tank #2	☐ Yes 🖼 No	☐ Yes ☐ Nõ	□ Yes XNo	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank		☐ Yes ☐ No	☐ Yes ☐ No	
	T drift Tarik	☐ Yes ☐ No	□ tes □ No	□ 162 □ 140	
	T STIP TSTIR	☐ Yes ☐ No	□ fes □ No	□ 162 □ 140]	
<u> </u>	of septage were removed?	.X. 2* 10			
Tank #1	of septage were removed?	gal Pretreatmen	t tank——— g	al Pump Tank	
Tank #1	of septage were removed?	gal Pretreatmen	t tank——— g	al Pump Tank	
Tank #1	of septage were removed?	gal Pretreatmen	t tank——— g	al Pump Tank	
Tank #1	of septage were removed? gal Tank #2 250 List any troubleshooting,	gal Pretreatmen	t tank——— g	al Pump Tank	

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934