

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.						
Date of Maintenance: 9/1/17 Reason for Maintenance: Routine						
Property Address: 1460 Newberry ave. Property Owner's Name: Mike Heints						
Municipality: Yast	Jakaland ZIP: 53	82 Property Ide	ntification Number	:	_ 0	
Maintenance Permit N	40: <u>£8009w814</u> 6	Maintainer Name a	nd License No	1EYER / 1915		
Maintena	ance Performed	Tank Meas	surement (must be	completed if tanks h	(OT pumped)	
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum	measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100						
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater					f 25% or greater	
1. Access used to remove septage: Maintenance Hole Other (enter authorization code)						
2. Were all covers securely replaced? 🖊 Yes 🗆 No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	d?				
Tank #1 1000	gal Tank #2 1000	gal Pretreatmen	t tankg	al Pump Tank	gal	
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
×						
6. Location of septage disposal:						