

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entiret	y to constitute a va	id maintenance pe	ermit. This permit m	ust be completed	
<u>prior</u> to performing maintenance activ	ities and remain on	site for the durati	on of the maintenance	ce activity.	
Date of Maintenance: 7-2517 Reaso	n for Maintenance:	Partine			
Property Address: 4310 Stillwater Ri	W. Mc F	roperty Owner's Na	ame: Harad	Cenverse	
Municipality: We Gmo ZIP:550	Property Idea	ntification Number:			
Maintenance Permit No: <u>N 1906 C 7148</u>	Maintainer Name ar	d License No. Pink	y's Environmental Sew	ver Service/ L1673	
				hyer-t-	
Maintenance Performed	Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of	Liquid Level of Tank ——— in			
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements	s) = % Sludge & Scr	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 2. Were all covers securely replaced? Yes 3. Is there evidence of tank leakage from a see evidence of damaged, cracked, or structum 	eptic, holding, pretr			ating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remove Tank #1 2000 gal Tank #2		tankg	al Pump Tank	gal	
Other information: List any troubleshooting Location of septage disposal:	g, minor repairs co		ty concerns, or other		
Pink	y's Environmental Se	ewer Service Inc.			

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673