

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	7 5 5 1 5		D KA	1	
Date of Maintenance: _	8-25-17 Reason f	or Maintenance: _	Keg Ma	ent	D (+1
Property Address:	150 Larkspur	Ave N P	roperty Owner's Na	me://avshall+	Paula Johnson
Municipality: 1960	- ne ZIP: 550	<u>4</u> 7 Property Iden	tification Number:		<del>-</del>
Maintenance Permit No	: 6869068075 M	aintainer Name an	d License No. Smili	e's Sewer Service/L	2428
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
550 - 60 ap. 2000	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage:   Maintenance Hole Other (enter authorization code)  Pre 1980					
2. Were all covers securely replaced?   Yes No *					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or					
evidence of damaged, cracked, or structurally unsound maintenance hole covers?   Yes					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 【Mo	☐ Yes ☐No	☐ Yes C No	10
2	Septic/Holding Tank #2	☐ Yes 【☐ No	☐ Yes 乙★ Yo	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 Zongal Tank #2 Zologal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
1000 Cand ASV					
6. Location of septage disposal:					

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934