

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a va	id maintenance p	ermit. This permit	must be completed
prior to perfo	rming maintenance activitie	es and remain on	site for the durat	ion of the maintena	nce activity
Date of Maintenance:	31.12	or Maintenance: _	0	e	rice delivity.
Property Address: 9	030 64th St. N	P	roperty Owner's N	ame: Mire & C	aseu Fech
Municipality: <u>Shill</u>			tification Number		
Maintenance Permit N	40: <u>V8545 r 6705</u> Ma	aintainer Name an	d License No. Pink	y's Environmental Se	ewer Service/ L1673
Maintena	ance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank — in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence	curely replaced?  Yes of tank leakage from a septinged, cracked, or structural  Tank	ic, holding, pretro	eatment or pump enance hole cove Leaking In	tank below the oper rs? Yes No	rating depth or
	Septic/Holding Tank #1		./		
	Septic/Holding Fallk #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	$\square$ Yes $\square$ No	☐ Yes ☐ No	☐ Yes ☐ No	
A	of septage were removed?				
Tank #1 /250		gal Pretreatment		al Pump Tank	gal
5. Other information  — Druped	: List any troubleshooting, r Through Pipe	minor repairs con		pool on	fank
6. Location of septage	e disposal:				
	Dialasta	Facilities and the first			

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673