

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entire	ty to constitute a v	alid maintenance	permit. This permit	must be completed	
prior to performing maintenance activ	on for Maintenance:	Ruthil		nce activity.	
Property Address: 1780 Quartin Ava	Sc.	Property Owner's	Name: GANA M	lamn	
Municipality: Carelona ZIP: 55	Property Ide	entification Numbe	r:	CVIII	
Maintenance Permit No: 1162517673	Maintainer Name a	and License No. Pin	ky's Environmental So	Wor Consider / L4472	
			ny s Environmentat se	wer service/ L16/3	
Maintenance Performed	Tank Mea	surement (must b	e completed if tanks	NOT pumped)	
Tank(s) Pumped	The state of the s	Tank — in			
Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements	s) = % Sludge & Sc	ALL THE REAL PROPERTY AND ADDRESS OF THE PARTY	anks must be pumped		
Is there evidence of tank leakage from a se evidence of damaged, cracked, or structu	rally upgoind and	- admiring	rank nelow the obel		
Tank	Leaking Out	tenance hole cove	Prs? Yes No Cover Damage	ating depth or	
		tenance hole cove	ers? Yes No	ating depth or	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out	Leaking In	Cover Damage	ating depth or	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No	Leaking In Yes	Cover Damage Yes No Yes No	ating depth or	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No Yes No	Leaking In Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	ating depth or	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No Yes No		
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank 4. How many gallons of septage were removed Tank #1	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No Yes No	and.	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No Area N	Cover Damage Yes No Yes No Yes No Yes No Yes No Person	gal	

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001