

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

prior to performing maintenance activiti	o constitute a v	alid maintenance p	ermit. This permit n	nust be completed	
prior to performing maintenance activiti	es and remain of	n-site for the durat	ion of the maintenar	ice activity.	
Date of Maintenance: $8-3-17$ Reason 1	for Maintenance:	_ Routine			
Property Address: <u>2289 River Rd S.</u>		Property Owner's N	ame: Stanley	Hubband	
Municipality: <u>Lakeland</u> zIP: <u>550</u>	43 Property Ide	entification Number	:		
Maintenance Permit No: 05352n7180 M	aintainer Name a	nd License No. Pink	v's Environmental Sev	wer Sensice / 14472	
			y s chiviloninientat sev	Wel Service/ L16/3	
Maintenance Performed	Tank Mea	surement (must be	completed if tanks I	NOT pumped)	
Tank(s) Pumped	CONTRACTOR OF THE PARTY OF THE	Tank — in			
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?	Sludge + Scum	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage:   Maintenance	ce Hole Other (				
2. Were all covers securely replaced?  Yes			ac) Difference	(h.h.)	
3. Is there evidence of tank leakage from a sept	ic, holding, pret	reatment or pump	tank below the opera	ating depth or	
evidence of damaged, cracked, of structural	ly unsound main	tenance hole cove	rs? Yes No	acing depth of	
evidence of damaged, cracked, or structural  ———————————————————————————————————	Leaking Out	Leaking In	rs?	acing depth of	
			rs? 🗌 Yes 🗆 No	acing depth of	
Tank	Leaking Out	Leaking In	rs?  Yes  No Cover Damage	ating depth of	
Tank Septic/Holding Tank #1	Leaking Out  Yes No	Leaking In  Yes No	Cover Damage  Yes No	acing depth of	
Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out  Yes No Yes No	Leaking In  Yes No Yes No	Cover Damage  Yes No Yes No Yes No	acing depth of	
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed?	Leaking Out  Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No Yes No Yes No	Yes No  Cover Damage  Yes No  Yes No  Yes No  Yes No  Yes No		
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed?	Leaking Out  Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No Yes No Yes No	Yes No  Cover Damage  Yes No  Yes No  Yes No  Yes No  Yes No		
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank	Leaking Out  Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No Yes No Yes No	Yes No  Cover Damage  Yes No  Yes No  Yes No  Yes No  Yes No	gal	
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were removed?  Tank #1	Leaking Out  Yes No Yes No Yes No Yes No	Leaking In  Yes No Yes No Yes No Yes No Yes No	Yes No  Cover Damage  Yes No  Yes No  Yes No  Yes No  Yes No	gal	

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673