

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

Subsurface Sewage Treatment System Maintenance Permit

	ompleted in its entirety t	o constituto a vali	d maintenance per	mit. This permit mus	st be completed
This section must be c	ompleted in its entirety t	o constitute a van	ito for the duratio	n of the maintenance	activity.
prior to perform	ning maintenance activition)	II of the manterians	
Date of Maintenance: _		for Maintenance: $\frac{1}{4}$		0.000	C 100 -
Property Address: <u></u>	197 Wallone	BCM_ Pr	operty Owner's Na	me: 30500 S	Magi
Municipality: \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		Property Iden			_
Maintenance Permit No	:V5738K7150M	laintainer Name and	d License No. Pinky	's Environmental Sewe	er Service/ L1673
	ve Porformed	Tank Measi	urement (must be	completed if tanks NO	OT pumped)
Maintenance Performed					
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped? Yes No (if no provide measurements)		Eldid Ecret of Talix			
		Studge Level III Talk			
		Studge + Scull / Elquid Edvet			
		70 510 45 5 10 10 10 10 10 10 10 10 10 10 10 10 10			
1. Access used to rem	nove septage: Maintena	nce Hole Mother (e	nter authorization co	de)	
	curely replaced? 🎾 Yes				
3. Is there evidence of	of tank leakage from a sep aged, cracked, or structur	tic, holding, pretr	eatment or pump t tenance hole cove	tank below the opera rs? Yes No	ting depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	1?			
Tank #1 1300	2 gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information	: List any troubleshooting	on Syst	nducted, tank safe	ety concerns, or othe	
	e disposal:				
6. Location of septag	e disposat:	The Vester Selfor			
			6 1 1		

Pinky's Environmental Sewer Service Inc.

PO Box 354

Afton MN 55001

P: 651-439-4847 License Number: L1673