

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

prior to perior	illing manicenance activities			·	
Date of Maintenance:	8-28-17 Reason f	or Maintenance: _	Cleaning		
Property Address: 11533 Tronwood Ave Property Owner's Name: Bill Jacobson					
Municipality: 54.00	water ZIP: 5508	∂ Property Ider	tification Number:		
	: 1708 V 8112 M				<u> </u>
	,				
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
☐ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements)		Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in			
		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: Maintenan	ce Hole 🗌 Other (e	nter authorization co	ode)	
2. Were all covers securely replaced? Yes No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or					
evidence of damaged, cracked, or structurally unsound maintenance hole covers? 🔲 Yes 🗔 No					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ⊑¶o	☐ Yes ☐ N o	☐ Yes ☐1√10	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Tank #1 1,500	of septage were removed? _ gal Tank #2 <u>/ 0 60</u> : List any troubleshooting,	gal Pretreatmen			
6. Location of septage disposal:					

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934