

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped Sludge and scum r Do tanks need to	neasured	Liquid Level of T Sludge Level in T Sludge + Scum _ = % Sludge & Scu	ank in ank in / Liquid L	Scum Level in Tank evel X 100 nks must be pumped	in
		ance Hole Other (e	nter authorization co	ode)	
3. Is there evidence	ecurely replaced? Yes of tank leakage from a se	i □ No eptic, holding, pretr	eatment or pump	tank below the ope	rating depth or
2. Were all covers se 3. Is there evidence	ecurely replaced? 💋 Yes	i □ No eptic, holding, pretr	eatment or pump	tank below the ope	rating depth or
2. Were all covers se 3. Is there evidence	ecurely replaced? A Yes of tank leakage from a se aged, cracked, or structu	No Poperic, holding, pretrairally unsound main	eatment or pump tenance hole cove Leaking In	tank below the opeers? Yes No Cover Damage	rating depth or
2. Were all covers se 3. Is there evidence	ecurely replaced?	No Poptic, holding, pretr Prally unsound main Leaking Out	eatment or pump tenance hole cove Leaking In	tank below the ope ers? Yes No Cover Damage	rating depth or
2. Were all covers se 3. Is there evidence	of tank leakage from a seaged, cracked, or structu Tank Septic/Holding Tank #1	No eptic, holding, pretrally unsound main Leaking Out	eatment or pump tenance hole cove Leaking In Yes No Yes No	tank below the ope ers? Yes No Cover Damage	rating depth or
2. Were all covers se 3. Is there evidence	recurely replaced? Yes of tank leakage from a se aged, cracked, or structu Tank Septic/Holding Tank #1 Septic/Holding Tank #2	No eptic, holding, pretrurally unsound main Leaking Out Yes ANO	Leaking In Yes No Yes No	tank below the opeers?	rating depth or

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934