

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: $\frac{85-17}{}$ Reaso	n for Maintenance:	Pa 174	67		
Property Address: 18360 Manning			ame: Dense	Lucatio	
Municipality: Manual ZIP: 53	ベイバフ	ntification Number:			
2/02/750	Maintainer Name ar			2429	
Maintenance Permit No: X ) 5 80 6/5 87	Maintainer name ai	ia License no. <u>simi</u>	ie s sewer service/i		
AANMANIA MANAMANIA M		r-Nawniuminasa su kantan in ni 1720.			
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped	11 *	Liquid Level of Tank in			
Sludge and scum measured	II -	Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped?	= % Sludge & Sci		nks must be pumped		
☐ Yes ☐ No (if no provide measurements	s)				
1. Access used to remove septage: Mainten	nance Hole 🗌 Other (e	enter authorization co	ode)		
2. Were all covers securely replaced? Yes	s 🗆 No				
3. Is there evidence of tank leakage from a se		reatment or pump	tank below the ope	erating depth or	
<del>_</del>	-  - ··· -   - · - · - · - · - · - ·	• •			
evidence of damaged, cracked, or structs	• • •		4	<b>,,,</b>	
evidence of damaged, cracked, or structs  Tank	• • •		4	]	
	urally unsound main	tenance hole cove	ers? 🗌 Yes 🗍 No	]	
Tank	urally unsound main	tenance hole cove	Cover Damage		
Tank Septic/Holding Tank #1	Leaking Out  Yes Ko	Leaking In  Yes No	Cover Damage  Yes ANO		
Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out  Yes Ano	Leaking In  Yes No  Yes No	Cover Damage  Yes ANO  Yes ANO		
Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out  Yes No  Yes No	Leaking In  Yes No  Yes No  Yes No	Cover Damage  Yes ANO Yes ANO Yes ANO		
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were remove	Leaking Out  Leaking Out  Yes Mo  Yes No  Yes No  Yes No	Leaking In  Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No		
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were remove Tank #1 / Off gal Tank #2	Leaking Out  Leaking Out  Yes No  Yes No  Yes No  Yes No  gal Pretreatmen	Leaking In  Yes No Yes No Yes No Yes No	Pers? ☐ Yes ☐ No  Cover Damage  ☐ Yes ☐ No  ☐ Yes ☐ No	gal	
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were remove	Leaking Out  Leaking Out  Yes No  Yes No  Yes No  Yes No  gal Pretreatmen	Leaking In  Yes No Yes No Yes No Yes No	Pers? ☐ Yes ☐ No  Cover Damage  ☐ Yes ☐ No  ☐ Yes ☐ No	gal	
Tank  Septic/Holding Tank #1  Septic/Holding Tank #2  Pretreatment Tank  Pump Tank  4. How many gallons of septage were remove Tank #1 / Off gal Tank #2	Leaking Out  Leaking Out  Yes No  Yes No  Yes No  Yes No  gal Pretreatmen	Leaking In  Yes No Yes No Yes No Yes No	Pers? ☐ Yes ☐ No  Cover Damage  ☐ Yes ☐ No  ☐ Yes ☐ No	gal	

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934