

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

		Tank Mass	livamente/miligi ba	completed (Capits	NO E AUTORY)
Maintenance Performed  ☐ Tank(s) Pumped ☐ Sludge and scum measured ☐ Do tanks need to be pumped? ☐ Yes ☐ No (if no provide measurements)		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to re-	move septage: 🔼 Mainten	ance Hole 🗌 Other (6	enter authorization co	ode)	•
2. Were all covers se	saranafir nandaaada Milyoc	. L No			
3. Is there evidence	ecurely replaced? Yes of tank leakage from a se aged, cracked, or structu Tank	eptic, holding, preti	reatment or pump tenance hole cove Leaking In	tank below the operers?  Yes No	rating depth or
3. Is there evidence	of tank leakage from a se aged, cracked, or structu	eptic, holding, pretr rally unsound main Leaking Out	tenance hole cove	ers? 🗌 Yes 💆 No	rating depth or
3. Is there evidence	of tank leakage from a se aged, cracked, or structu Tank	eptic, holding, pretr rally unsound main	Leaking In	Cover Damage	rating depth or
3. Is there evidence	of tank leakage from a seaged, cracked, or structu  Tank  Septic/Holding Tank #1	eptic, holding, pretr rally unsound main Leaking Out	Leaking In  Yes No	Cover Damage  Yes No	rating depth or
3. Is there evidence	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out  Yes No	Leaking In  Yes No  Yes No	Cover Damage  Yes No  Yes No  Yes No	rating depth or

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934