

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	9-6-17 Reason	n for Maintenance: _	Routine		
Property Address:	166 Justen Trl A	/ Р	roperty Owner's N	ame: Tim	Johnson
Municipality: Stille	vater ZIP: 55	Property Ider	tification Number:		
Maintenance Permit N	o: r7485g8453	Maintainer Name an	d License No. <u>Smil</u>	ie's Sewer Service	/L2428
	nce Restormed	Tank Meas	urement (must be	(completed if tan	ks NOT pumped)
Tank(s) Pumped  Sludge and scum measured Do tanks need to be pumped?  Yes No (if no provide measurements)		Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
<ol> <li>Were all covers se</li> <li>Is there evidence</li> </ol>	nove septage: Amainten curely replaced? Amainten of tank leakage from a se aged, cracked, or structu	□ No eptic, holding, pretr	eatment or pump	tank below the o	
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🏿 No	☐ Yes 🖾No	☐ Yes ☑No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes 🗷 No	☐ Yes 🏿 No	☐ Yes ☒-No	
Tank #1_1250	of septage were remove gal Tank #2 : List any troubleshootin	gal Pretreatmen	t tank g	al Pump Tanke	300 gal other concerns.

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934