

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	Reason	for Maintenance: _	Reg Man	+		
Property Address: 13	2700 181st S	7 N F	Property Owner's Na	ame: Pat+Mit	relle Wolev,	
Municipality: <u>Mar</u>	ine zip:550	Property Ider	ntification Number:		<u></u>	
Maintenance Permit No	0:00786K8612	, Maintainer Name ar	nd License No. <u>Smili</u>	ie's <u>Sewer Service/L</u>	2428	
	V					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured			Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100			
Do tanks need to be pumped?		= % Studge & Scum Tanks must be pumped if 25% or greater				
Yes No (if I	no provide measurements)				<u>-</u>	
1. Access used to ren	nove septage: Maintena	ance Hole \square Other (6	enter authorization co	ode)		
2. Were all covers se	curely replaced? Tyes	□No				
3. Is there evidence	of tank leakage from a se	ptic, holding, preti	reatment or pump	tank below the ope	erating depth or	
evidence of dama	aged, cracked, or structu	rally unsound main	tenance hole cove	rs? 🗌 Yes 🖾 No		
	Tank	Leaking Out	Leaking In	Cover Damage	·	
			Leaking In Yes Ano			
	Tank	Leaking Out		Cover Damage		
	Tank Septic/Holding Tank #1	Leaking Out Yes No	☐ Yes Ano	Cover Damage Ves No		
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No	☐ Yes ☐ No	Cover Damage Yes No Yes No		
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	Cover Damage Yes No Yes No Yes No		
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No Yes No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	Cover Damage Yes No Yes No Yes No		
Tank #1/25	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No Yes No	Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No		
Tank #1/25	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	Leaking Out Yes No Yes No Yes No Yes No Yes No	Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No		
Tank #1/25	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No Yes No	Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No		
Tank #1/25	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2 : List any troubleshooting	Leaking Out Yes No Yes No Yes No Yes No Yes No	Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No		

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934