

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance: Property Address: Municipality Maintenance Permit No	326 14895t Docter_zip650	Property Ider	roperty Owner's Na atification Number:		affer—
Maintenance Performed  Tank(s) Pumped  Sludge and scum measured Do tanks need to be pumped?  Yes No (if no provide measurements)		Tank Measurement (must be completed if tanks NOT pumped)  Liquid Level of Tank in  Sludge Level in Tank in Scum Level in Tank in  Sludge + Scum / Liquid Level X 100  = % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers see 3. Is there evidence of	nove septage: Amaintena curely replaced? A Yes of tank leakage from a se aged, cracked, or structur	□ No ptic, holding, pretr rally unsound main	eatment or pump tenance hole cove	tank below the opers? \( \text{Yes \text{Yes}} \)	rating depth or
	Tank	Leaking Out	Leaking In  Ves Mo	Cover Damage  ☐ Yes  ☑ No	
		☐ Yes 🖾 No	•		
	Septic/Holding Tank #2	☐ Yes 📈 No		☐ Yes ☑No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes 🗗 No	☐ Yes ☑ No	☐ Yes No	
Tank #1/000	of septage were remove gal Tank #2/000 : List any troubleshootin	gal Pretreatmen	t tankg nducted, tank safe	al Pump Tank <u>10</u> ety concerns, or oth	gal ner concerns.

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934