

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT
GOVERNMENT CENTER
14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

	930 130 FL ST					
	ater ZIP:55					
Maintenance Permit No	:w6201 n8731	Maintainer Name an	d License No. Smili	ie's Sewer Service/	'L2428	
	!					
Maintenar	ce Performed	Tank Meas	urement (must be	completed if tank	s NOT pumped)	
Tank(s) Pumped Sludge and scum measured Do tanks need to be pumped?		Liquid Level of T	Liquid Level of Tank in Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater			
		Sludge Level in				
		= % Sludge & Scum _				
☐ Yes ☐ No (if r	o provide measurements)			.	
1. Access used to rem	ove septage: Mainten	ance Hole 🗌 Other (e	nter authorization co	ode)		
2. Were all covers sec	urely replaced? 📈 Yes	□No				
 Were all covers securely replaced? ✓ Yes □ No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or 						
evidence of dama	ged, cracked, or structu	rally unsound main	tenance hole cove	ers? 🔲 yes 🌠 No	1	
C TIGGING OF GAING	ged, clucked, or structu					
cridence of dame	Tank	Leaking Out	Leaking In	Cover Damage		
evidence of dama		Leaking Out		Cover Damage		
Cridence of dama	Tank	Leaking Out ☐ Yes 🌠 No	Leaking In	Cover Damage Yes No		
cyractice of dama	Tank Septic/Holding Tank #1	Leaking Out ☐ Yes 🌠 No	Leaking In ☐ Yes ☑ No ☐ Yes ☑ No	Cover Damage Yes No Yes No		
criticist of dame	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out ☐ Yes 🎾 No ☐ Yes 🞾 No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No		
Cridence of dama	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No		
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No		
4. How many gallons Tank #1 1500	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal	
4. How many gallons Tank #1 1500	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal	
4. How many gallons Tank #1 1500	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal	
4. How many gallons Tank #1 1500 5. Other information	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No Yes No Res No Res Res Res	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal	
4. How many gallons Tank #1 1500	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were remove gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal	

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934