

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	9-8-12 Reason f	or Maintenance:	Rea Mi	aint	
Property Address: 1883 Everton Ave N Property Owner's Name: Brian Dafrene					
Municipality: For	-1 / K ZIP:5502	S Property Ider	tification Number:		
Maintenance Permit No	2000	_		e's Sewer Service/L	2428
Maintenance remit in	5. <u>77 - 70 - 70 - 70</u>				
Maintenance Performed  Tank(s) Pumped  Sludge and scum measured		Tank Measurement (must be completed if tanks NOT pumped)			
		Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100   = % Sludge & Scum Tanks must be pumped if 25% or greater			
☐ Yes ☐ No (if no provide measurements)					_
1. Access used to remove septage: Maintenance Hole  Other (enter authorization code)					
<ul> <li>2. Were all covers securely replaced? Yes \( \subsetention \text{No} \)</li> <li>3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? \( \subseteq \text{ Yes } \subseteq \text{No} \)</li> </ul>					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ♠No	☐ Yes ☐No	☐ Yes ☐No	ļ
	Septic/Holding Tank #2	☐ Yes 🗖 No	☐ Yes 🖒 No	☐ Yes ☐No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	i
	Pump Tank	☐ Yes 🖟 No	☐ Yes ☐ No	☐ Yes ☐No	
4. How many gallons of septage were removed?  Tank #1  gal Tank #2  gal Pretreatment tank gal Pump Tank gal  5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
Tank #1 <u>(NOO</u> 5. Other information	gal Tank #2 ////	gal Pretreatmen	t tank g nducted, tank safe	al Pump Tank \( \frac{\lambda}{c} \)	gal gal gal

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073

License# 2428 P: 651-433-3934