

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance p	ermit. This permit n	nust be completed		
<u>prior</u> to perfor	ming maintenance activit	ies and remain on	-site for the durat	ion of the maintenar	nce activity.		
Date of Maintenance:	9/5/17 Reason	for Maintenance:	Routine				
Property Address: 14	9/5/17 Reason 30th St.	n	Property Owner's N	ame: Kent Sch	ollmeier		
Municipality: Waste	Lakeland IIP: 550	2022 Property Ide	ntification Number	:			
Maintenance Permit N	o: <u>X1343j8154</u> h	Maintainer Name ar	nd License No. <u> </u>	Jeyer / 1913	5		
Maintenai	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)		
Tank(s) Pumped		Liquid Level of Tank in					
☐ Sludge and scum m	neasured	Sludge Level in	Tank in	Scum Level in Tank.	in		
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100							
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater							
2. Were all covers see3. Is there evidence of	nove septage: Maintena curely replaced? Yes of tank leakage from a sep ged, cracked, or structur	\square No otic, holding, preti	eatment or pump	tank below the oper	rating depth or		
	Tank	Leaking Out	Leaking In	Cover Damage			
	Septic/Holding Tank #1	☐ Yes 🗖 No	☐ Yes ☐No	☐ Yes ☐ No			
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	Yes □ No			
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No			
4. How many gallons	of septage were removed	?					
it ito it illustry gallotte		Tank #1 1500 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal					
		gal Pretreatmen	t tankg	al Pump Tank	gal		
Tank #1 1500							
Tank #1 1500	gal Tank #2 1000						
Tank #1 1500	gal Tank #2 1000						