

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006
Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.

Date of Maintenance:	9-21-17 Reason	for Maintenance: _	Cleanian	<u></u>		
Property Address:/_	- 1 1	/ P		ame: Rebected	Thorstad	
Municipality: 54:66	1	82 Property Ider				
	: W7258 28714				L2428	
Maintenance remit no	,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
Mainténan	ce Performed	Tank Meas	urement (must be	completed if tanks	: NOT pumped)	
☐ Tank(s) Pumped ☐ Sludge and scum measured Do tanks need to be pumped?		Liquid Level of T	Liquid Level of Tank in			
		Sludge Level in Tank in Scum Level in Tank in				
		Sludge + Scum / Liquid Level X 100 = % Sludge & Scum Tanks must be pumped if 25% or greater				
Yes 🗌 No (if n	o provide measurements)	= % studge a sco	rai	ika muse be pumper	11 25% or greater	
1. Access used to rem	ove septage: Maintena	nce Hole 🗌 Other (e	enter authorization co	ode)		
	curely replaced? Yes					
	f tank leakage from a se	ntic holding pretr	eatment or nump	tank below the op-	erating depth or	
3. Is there evidence of	it tank leakage itoili a sej	pere, motaling, preed	catinetic or pamp		or manning and provides	
a. Is there evidence of dama	ged, cracked, or structur	ally unsound main	tenance hole cove	rs? ☐ Yes ☐ No	or word	
evidence of dama	ged, cracked, or structur	Tally unsound main	tenance hole cove	rs? Yes No Cover Damage		
evidence of dama	ged, cracked, or structur	ally unsound main	tenance hole cove	rs? 🗌 Yes 🖼 No		
evidence of dama	ged, cracked, or structur	Leaking Out	tenance hole cove	rs? Yes No		
evidence of dama	ged, cracked, or structur Tank Septic/Holding Tank #1	Leaking Out	Leaking In Yes No	Cover Damage Yes No		
evidence of dama	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes Mo	Leaking In Yes No Yes Mo	Cover Damage Yes No Yes No		
evidence of dama	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	Leaking Out Yes Mo Yes Mo Yes Mo	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No		
evidence of dama	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Leaking Out Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No		
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	rs?	gal	
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	rs?	gal	
4. How many gallons	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed gal Tank #2	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	rs?	gal	

Smilie's Sewer Service 23893 Pomroy Ave N Scandia, MN 55073 License# 2428 P: 651-433-3934